


Flow Chart



bar	Nm max	ft.lbs max
2	495	364
3	625	461
4	790	583
5	970	714
6	1185	874
7	1450	1071

Operating pressure on the machine
Air Consumption: 21 - 32 cfm.

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 1000R

Model

4-130-

Equipment Serial Number

Date of Delivery



TITAN
 TECHNOLOGIES INTERNATIONAL, INC.

SUPERIOR BOLTING SOLUTIONS

www.TitanTi.com