


Flow Chart



bar	Nm max	ft.lbs max
2	910	670
3	1150	848
4	1455	1073
5	1780	1314
6	2180	1609
7	2670	1970

Operating pressure on the machine
Air Consumption:
 21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 2000R

Model

16-71-

Equipment Serial Number

Date of Delivery

