


## Flow Chart



### Torque table

bar	Nm max	ft.lbs max
2	135	98
3	170	124
4	215	157
5	260	192
6	320	235
7	390	288

Operating pressure  
on the machine

Air Consumption:  
21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

## TECHNICAL DATA

### AIR-Tite

### AT 290R

Model

### 4-35-

Equipment Serial Number

Date of Delivery



## TITAN

TECHNOLOGIES INTERNATIONAL, INC.  
SUPERIOR BOLTING SOLUTIONS

www.TitanTI.com