


Flow Chart



Torque table		
Gear II bar	Nm max	ft.lbs max
2	840	620
3	1065	784
4	1344	991
5	1645	1214
6	2015	1487
7	2470	1821
Gear I bar	Nm max	ft.lbs max
2	2675	1973
3	3385	2496
4	4280	3157
5	5245	3867
6	6420	4736
7	7865	5801

Operating pressure on the machine

Air Consumption: 21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 5800F-2

Model

20-7-

Equipment Serial Number

Date of Delivery



TITAN
TECHNOLOGIES INTERNATIONAL, INC.

SUPERIOR BOLTING SOLUTIONS

www.TitanTi.com