


Flow Chart



Torque table		
Gear II bar	Nm max	ft.lbs max
2	1010	744
3	1275	940
4	1615	1190
5	1975	1457
6	2420	1784
7	2965	2185

Gear I bar	Nm max	ft.lbs max
2	3210	2368
3	4060	2995
4	5135	3789
5	6290	4640
6	7705	5683
7	9435	6961

Operating pressure on the machine
Air Consumption:
 21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 7000F-2

Model

24-7-

Equipment Serial Number

Date of Delivery

