


Flow Chart



Torque table		
bar	Nm max	ft.lbs max
2	3330	2458
3	4215	3109
4	5330	3932
5	6530	4816
6	8000	5898
7	9795	7224

Operating pressure on the machine
Air Consumption: 21 - 32 cfm.

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 7200R

Model

28-170-

Equipment Serial Number

Date of Delivery



www.TitanTI.com