


Flow Chart



Torque table

Gear II bar	Nm max	ft.lbs max
2	120	89
3	150	112
4	190	142
5	235	173
6	290	212
7	355	260

Gear I bar	Nm max	ft.lbs max
2	380	282
3	485	357
4	610	451
5	750	552
6	915	677
7	1125	829

Operating pressure on the machine
Air Consumption:
 21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 800F-2

Model

4-5-

Equipment Serial Number

Date of Delivery

