



Pressure Vs Torque Conversion Chart			
<i>Titan LP16 Low Profile</i>			
Pressure	<i>Torque</i>		Pressure
Psi	<i>Ft-Lb</i>		Mpa
			<i>Nm</i>
1500	2360		10
1600	2518		11
1800	2832		12
2000	3174		14
2200	3491		15
2400	3808		17
2600	4126		18
2800	4443		19
3000	4820		21
3200	5142		22
3400	5463		23
3600	5784		25
3800	6106		26
4000	6475		28
4200	6799		29
4400	7123		30
4600	7447		32
4800	7770		33
5000	8156		34
5200	8482		36
5400	8808		37
5600	9134		39
5800	9460		40
6000	9789		41
6200	10116		43
6400	10442		44
6600	10768		46
6800	11095		47
7000	11504		48
7200	11833		50
7400	12162		51
7600	12490		52
7800	12819		54
8000	13046		55
8200	13372		57
8400	13698		58
8600	14024		59
8800	14350		61
9000	14700		62
9200	15027		63
9400	15353		65
9600	15680		66
9800	16007		68
10000	16231		69