



Pressure Vs Torque Conversion Chart			
<i>Titan LP32 Low Profile</i>			
Pressure	<i>Torque</i>		Pressure
Psi	<i>Ft-Lb</i>		Mpa
			<i>Nm</i>
1500	4896		10
1600	5222		11
1800	5875		12
2000	6528		14
2200	7181		15
2400	7834		17
2600	8486		18
2800	9139		19
3000	9792		21
3200	10445		22
3400	11098		23
3600	11750		25
3800	12403		26
4000	13056		28
4200	13709		29
4400	14362		30
4600	15014		32
4800	15667		33
5000	16320		34
5200	16973		36
5400	17626		37
5600	18278		39
5800	18931		40
6000	19584		41
6200	20237		43
6400	20890		44
6600	21542		46
6800	22195		47
7000	22848		48
7200	23501		50
7400	24154		51
7600	24806		52
7800	25459		54
8000	26112		55
8200	26765		57
8400	27418		58
8600	28070		59
8800	28723		61
9000	29376		62
9200	30029		63
9400	30682		65
9600	31334		66
9800	31987		68
10000	32640		69