



Pressure Vs Torque Conversion Chart			
<i>Titan LP8 Low Profile</i>			
Pressure	<i>Torque</i>		Pressure
Psi	<i>Ft-Lb</i>		Mpa
			<i>Nm</i>
1500	1075		10
1600	1146		11
1800	1290		12
2000	1488		14
2200	1637		15
2400	1785		17
2600	1934		18
2800	2083		19
3000	2289		21
3200	2442		22
3400	2594		23
3600	2747		25
3800	2899		26
4000	3028		28
4200	3180		29
4400	3331		30
4600	3483		32
4800	3634		33
5000	3878		34
5200	4033		36
5400	4188		37
5600	4343		39
5800	4498		40
6000	4704		41
6200	4860		43
6400	5017		44
6600	5174		46
6800	5331		47
7000	5545		48
7200	5704		50
7400	5862		51
7600	6021		52
7800	6179		54
8000	6364		55
8200	6523		57
8400	6682		58
8600	6841		59
8800	7000		61
9000	7163		62
9200	7322		63
9400	7481		65
9600	7641		66
9800	7800		68
10000	8024		69