



Superior Bolting Solutions

#072704

Pressure Vs Torque Conversion Chart			
<i>Titan T1 Square Drive Wrench</i>			
Pressure	Torque		Pressure
Psi	Ft-Lb		Mpa
			Nm
1500	197		10
1600	210		11
1800	236		12
2000	271		14
2200	298		15
2400	325		17
2600	352		18
2800	379		19
3000	411		21
3200	438		22
3400	465		23
3600	493		25
3800	520		26
4000	549		28
4200	577		29
4400	604		30
4600	632		32
4800	659		33
5000	686		34
5200	714		36
5400	741		37
5600	769		39
5800	796		40
6000	824		41
6200	852		43
6400	879		44
6600	907		46
6800	934		47
7000	962		48
7200	990		50
7400	1017		51
7600	1045		52
7800	1072		54
8000	1098		55
8200	1125		57
8400	1153		58
8600	1180		59
8800	1208		61
9000	1233		62
9200	1261		63
9400	1288		65
9600	1315		66
9800	1343		68
10000	1359		69

9001 Jameel Road, Suite 180 • Houston, TX 77040

Toll Free: 866.345.8484 • Phone: 281.449.9994 • Fax: 281.449.9996 • Email: sales@titanti.com