



Superior Bolting Solutions

#061204

Pressure Vs Torque Conversion Chart			
<i>Titan T10 Square Drive Tool</i>			
Pressure	<i>Torque</i>	Pressure	<i>Torque</i>
Psi	<i>Ft-Lb</i>	Mpa	<i>Nm</i>
1500	1662	10	2254
1600	1773	11	2404
1800	1994	12	2704
2000	2236	14	3032
2200	2460	15	3335
2400	2683	17	3638
2600	2907	18	3942
2800	3130	19	4245
3000	3365	21	4563
3200	3589	22	4867
3400	3814	23	5171
3600	4038	25	5476
3800	4262	26	5780
4000	4456	28	6042
4200	4679	29	6344
4400	4902	30	6647
4600	5124	32	6949
4800	5347	33	7251
5000	5588	34	7577
5200	5812	36	7880
5400	6035	37	8184
5600	6259	39	8487
5800	6482	40	8790
6000	6717	41	9108
6200	6941	43	9412
6400	7165	44	9715
6600	7389	46	10019
6800	7613	47	10323
7000	7746	48	10504
7200	7967	50	10804
7400	8189	51	11104
7600	8410	52	11404
7800	8631	54	11704
8000	8867	55	12024
8200	9089	57	12324
8400	9310	58	12625
8600	9532	59	12925
8800	9754	61	13226
9000	10075	62	13662
9200	10299	63	13965
9400	10523	65	14269
9600	10747	66	14572
9800	10971	68	14876
10000	11067	69	15007

9001 Jameel Road, Suite 180 • Houston, TX 77040

Toll Free: 866.345.8484 • Phone: 281.449.9994 • Fax: 281.449.9996 • Email: sales@titanti.com