

Pressure Vs Torque Conversion Chart			
<i>Titan T25 Square Drive Tool</i>			
Pressure	<i>Torque</i>	Pressure	<i>Torque</i>
Psi	<i>Ft-Lb</i>	Mpa	<i>Nm</i>
1500	3726	10	5052
1600	3974	11	5389
1800	4471	12	6063
2000	5106	14	6924
2200	5617	15	7616
2400	6127	17	8308
2600	6638	18	9001
2800	7148	19	9693
3000	7704	21	10447
3200	8218	22	11143
3400	8731	23	11840
3600	9245	25	12536
3800	9758	26	13232
4000	10288	28	13951
4200	10802	29	14648
4400	11317	30	15346
4600	11831	32	16043
4800	12346	33	16741
5000	12894	34	17484
5200	13410	36	18184
5400	13926	37	18883
5600	14441	39	19582
5800	14957	40	20282
6000	15348	41	20812
6200	15860	43	21506
6400	16371	44	22199
6600	16883	46	22893
6800	17394	47	23587
7000	17778	48	24107
7200	18286	50	24796
7400	18794	51	25485
7600	19302	52	26173
7800	19810	54	26862
8000	20146	55	27318
8200	20650	57	28001
8400	21153	58	28684
8600	21657	59	29367
8800	22161	61	30050
9000	22510	62	30524
9200	23010	63	31202
9400	23510	65	31880
9600	24011	66	32558
9800	24511	68	33237
10000	24749	69	33560