



Pressure Vs Torque Conversion Chart			
<i>Titan T3 Square Drive Tool</i>			
Pressure	<i>Torque</i>		Pressure
Psi	<i>Ft-Lb</i>		Mpa
			<i>Nm</i>
1500	468		10
1600	499		11
1800	562		12
2000	644		14
2200	708		15
2400	773		17
2600	837		18
2800	902		19
3000	961		21
3200	1025		22
3400	1089		23
3600	1153		25
3800	1217		26
4000	1278		28
4200	1342		29
4400	1406		30
4600	1470		32
4800	1534		33
5000	1592		34
5200	1656		36
5400	1719		37
5600	1783		39
5800	1847		40
6000	1896		41
6200	1959		43
6400	2022		44
6600	2086		46
6800	2149		47
7000	2190		48
7200	2253		50
7400	2315		51
7600	2378		52
7800	2440		54
8000	2497		55
8200	2559		57
8400	2622		58
8600	2684		59
8800	2747		61
9000	2810		62
9200	2872		63
9400	2935		65
9600	2997		66
9800	3060		68
10000	3124		69