



Pressure Vs Torque Conversion Chart			
<i>Titan T8 Square Drive Tool</i>			
Pressure	<i>Torque</i>		Pressure
Psi	<i>Ft-Lb</i>		Mpa
			<i>Nm</i>
1500	1168		10
1600	1246		11
1800	1402		12
2000	1574		14
2200	1731		15
2400	1889		17
2600	2046		18
2800	2204		19
3000	2378		21
3200	2537		22
3400	2695		23
3600	2854		25
3800	3012		26
4000	3216		28
4200	3377		29
4400	3538		30
4600	3698		32
4800	3859		33
5000	3990		34
5200	4150		36
5400	4309		37
5600	4469		39
5800	4628		40
6000	4848		41
6200	5010		43
6400	5171		44
6600	5333		46
6800	5494		47
7000	5660		48
7200	5822		50
7400	5983		51
7600	6145		52
7800	6307		54
8000	6476		55
8200	6638		57
8400	6800		58
8600	6962		59
8800	7124		61
9000	7240		62
9200	7401		63
9400	7562		65
9600	7723		66
9800	7884		68
10000	8062		69