


# Flow Chart



Torque table		
Gear II bar	Nm max	ft.lbs max
2	170	127
3	220	161
4	275	203
5	335	249
6	415	305
7	505	373

Gear I bar	Nm max	ft.lbs max
2	550	405
3	695	512
4	880	648
5	1075	793
6	1315	972
7	1615	1190

**Operating pressure on the machine**  
**Air Consumption:**  
 21 - 32 cfm.

**Torque**

All curves are approximate values. Unstable compressed air values can cause deviations.

## TECHNICAL DATA

**AIR-Tite**

**AT 1200F-2**

Model

**4-7-**

Equipment Serial Number

Date of Delivery

