


Flow Chart



bar	Nm max	ft.lbs max
2	645	476
3	815	603
4	1035	762
5	1265	934
6	1550	1144
7	1900	1401

Operating pressure on the machine
Air Consumption: 21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 1400R

Model

4-170-

Equipment Serial Number

Date of Delivery



TITAN
 TECHNOLOGIES INTERNATIONAL, INC.

SUPERIOR BOLTING SOLUTIONS

www.TitanTi.com