


# Flow Chart



bar	Nm max	ft.lbs max
2	75	55
3	95	70
4	120	89
5	150	111
6	180	133
7	225	166

**Operating pressure on the machine**  
**Air Consumption:**  
 21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

## TECHNICAL DATA

**AIR-Tite**

**AT 160R**

Model

**4-20-**

Equipment Serial Number

Date of Delivery



**TITAN**  
 TECHNOLOGIES INTERNATIONAL, INC.

SUPERIOR BOLTING SOLUTIONS

www.TitanTi.com