


Flow Chart



bar	Nm max	ft.lbs max
2	2610	1925
3	3300	2435
4	4175	3080
5	5115	3775
6	6270	4620
7	7675	5660

Operating pressure on the machine
Air Consumption: 21 - 32 cfm.

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 5700R

24-170-

Model

Equipment Serial Number

Date of Delivery



TITAN
 TECHNOLOGIES INTERNATIONAL, INC.

SUPERIOR BOLTING SOLUTIONS

www.TitanTi.com